



1




2

Step 2 : 50% tighten  
screw at this stage.




3

Step 3 : After all parts  
are in right position,  
then 100% tighten up  
all screws before using.



4




A



x4

B



x4

C



x4

D



x4

E



x1