







ASSEMBLY INSTRUCTION

Name	Qty	Part Sketch
SCREW	4	
WASHER-1	4	
SPANNER	1	
TABLE TOP	1	
TABLE BODY	1	



1



2



3

INSERT THE TOP INTO THE FOUR CORNORS RESPECTIVELY (THEY ARE INDICATED AS A, B, C, D ACCORDINGLY)
ALIGNING THE SCREW HOLES
SCREWING IN FIRMLY